

New 147.2905

- (a) After a cessation of operations of 1 year the owner or operator shall plug and abandon the well in accordance with an EPA approved plan unless he:
 - (1) Provides notice to the Regional Administrator;
 - (2) Describes actions or procedures, satisfactory to the Regional Administrator, that the owner or operator will take to ensure that the well will not endanger USDWs during the period of temporary abandonment. These actions and procedures shall include compliance with the technical requirements applicable to active injection wells including notification within 30 days of injection termination and annual reports to the Regional Administrator on well status unless waived by the Regional Administrator.